

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Australia – Victoria No. 386 (T) of 2024 WEST BASS STRAIT – BARWON HEADS

Date: EFFECTIVE IMMEDIATELY

Details:

Mariners are advised that the Orungal Wreck south cardinal mark buoy (Q6+LFI W 15s) is missing.

The established position of the buoy was: 38° 17.316' S, 144° 30.632' E (WGS84).

The buoy shall be re-positioned as soon as practicable.

Mariners are advised to navigate with caution in the vicinity of the Orungal Wreck.

AUS Charts and Publications Affected: AUS143, AU439144, AU340145

Victorian Charts and publications affected: Nil

Further Notice: A further Notice will be issued.



Figure 1 Missing Orungal Wreck south cardinal mark buoy (Q6+LFI W 15s)

A handwritten signature in blue ink, appearing to read 'Simon Farrar', with a stylized, cursive script.

SIMON FARRAR
Director Safety Operations
Date: 16/9/2024